

MAINTENANCE & CLEANING

Prime Panels (FRP liner and FRP laminated panels) require a minimum amount of maintenance and care. However, when cleaning is necessary, the following materials and procedures are recommended. Always test a small area before proceeding.

Normal dirt and grime:

Clean panels by hand using a cloth, sponge, or soft brush; or clean with a pressure sprayer. Wash with a solution of warm water and mild detergent (Pine-Sol, Spic 'N Span, etc.). A 10% solution of trisodium phosphate in warm water may also be used. Rinse panels with clear water. Steam cleaning is acceptable in USDA inspected facilities.

Hard water spots:

Wash panels with a 10% solution of acetic acid in cold water. Rinse thoroughly.

Adhesive, oil, or difficult substances:

Use mineral spirits with a clean white cloth. Rinse thoroughly with clear water.

Note:

Avoid the use of abrasive products such as steel wool, Brillo, Comet, etc.

Nonwarranty: The information contained in this literature is presented in good faith and is believed to be accurate, but without guarantee. Conditions of use are beyond our control and all risks are assumed by the user. Nothing herein is a recommendation for uses which infringe valid patents or as extending a license under valid patents.



2651 Colt Road
Springfield, Illinois 62707

Phone 217-789-7898
800-990-3468
Fax: 217-789-7897

www.primepanels.com